

Controlgear

SIRIUS 3R Motor Feeders

Fuseless load feeders for direct start Type of coordination 1 and 2



3RA1 up to 100 A

Selection and ordering data

- Direct start
- Accessories

Page

5/2
5/10

Technical data 5/16
Description 5/25
Circuit diagrams 5/32
Dimensions 5/44



3RA5 up to 16 A with AS-Interface for busbar system 40 and 60 mm

Selection and ordering data


- Direct start
- Accessories

Page

5/33
5/34

Description 5/35
Dimensions 5/48

Fuseless load feeders for reversing duty Type of coordination 1 and 2



3RA1 up to 100 A

Selection and ordering data

- Reversing duty
- Accessories

Page

5/6
5/10

Technical data 5/16
Description 5/25
Circuit diagrams 5/32
Dimensions 5/44



3RA5 up to 16 A with AS-Interface for busbar system 40 and 60 mm

Selection and ordering data

- Reversing duty
- Accessories

Page

5/33
5/34

Description 5/35
Dimensions 5/48

Contactors for fitting weld-free fuseless load feeders



NEW

3RT11 up to 40 A

Selection and ordering data

- For self-assembly
- Accessories

Page

5/36
5/10

Technical data 5/36
Description 5/49
Dimensions 5/49

Controlgear

SIRIUS 3R Solid-State Soft Starters

SIKOSTART Solid-State Motor Controllers

1

2

3

4

5

SIRIUS 3RW30, 3RW31 solid-state soft starters for smooth start and slowing down of three-phase asynchronous motors (for snapping onto standard mounting rails)



SIRIUS 3RW30 soft starters up to 100 A
Soft starters with two-ramp control
SIRIUS 3RW31 up to 25 A

Page

Selection and ordering data

- | | |
|---------------------|------|
| • 3RW30 up to 100 A | 5/50 |
| • 3RW31 up to 25 A | 5/50 |
| • Accessories | 5/51 |

Technical data	5/53
Description	5/56
Connection example	5/56
Dimensions	5/74

3RW34 SIKOSTART solid-state motor controllers for smooth start and slowing down of three-phase asynchronous motors



3RW34 SIKOSTART up to 1720 A


Page

Selection and ordering data

- | | |
|--------------------|------|
| • Standard circuit | 5/58 |
| • Root 3 circuit | 5/58 |
| • Accessories | 5/59 |
| • Spare parts | 5/59 |

Technical data	5/60
Description	5/63
Connection example	5/64
Dimensions	5/74

3RW22 SIKOSTART solid-state motor controllers for smooth start and slowing down, energy saving and DC braking of three-phase asynchronous motors



3RW22 SIKOSTART up to 70 A

Page

Selection and ordering data

- | | |
|---------------------------------------|------|
| • Standard version | 5/65 |
| • With electronic overload protection | 5/65 |
| • Accessories | 5/66 |
| • Spare parts | 5/66 |

Technical data	5/68
Description	5/73
Dimensions	5/76



3RW22 SIKOSTART up to 1200 A

Page

Selection and ordering data

- | | |
|--|------|
| • With electronic overload protection and serial interface | 5/65 |
| • Accessories | 5/66 |
| • Spare parts | 5/66 |

Technical data	5/68
Description	5/73
Dimensions	5/76