

Controlgear Overload Relays

Thermally delayed overload relays



**3RU11 overload relays up to 100 A
Class 10**

Page

Selection and ordering data

- With screw/Cage-Clamp connection 4/4
- Accessories 4/6

Technical data	4/7
Description	4/12
Circuit diagrams	4/13
Dimensions	4/53



**3UA overload relays up to 205/820 A
Class 10**

Page

Selection and ordering data

- For snap-on and screw mounting 4/31
- Accessories 4/33

Technical data	4/34
Description	4/37
Circuit diagrams	4/38
Dimensions	4/53

Solid-state overload relays



**3RB10 overload relays up to 100 A
Class 10 and Class 20**

Page

Selection and ordering data

- With screw connection 4/14
- Accessories 4/16

Technical data	4/17
Description	4/20
Circuit diagrams	4/21
Dimensions	4/53



**3RB12 overload relays up to 800 A
Class 5 to Class 30**

Page

Selection and ordering data

- Standard version 4/22
- With analog output 4/23
- Accessories 4/24

Technical data	4/25
Description	4/28
Circuit/connection diagrams	4/30
Dimensions	4/53

Thermistor motor protection



3RN10 thermistor motor protection for PTC temperature sensors

Page

Selection and ordering data

- 3UN2 --> 3RN10 recoding 4/38
- For screw and Cage Clamp connection 4/40
- Accessories 4/40

Technical data	4/41
Description	4/41
Circuit diagrams	4/44
Typical circuit diagrams	4/45
Dimensions	4/55

DC adapter



7PX80 direct voltage adapter


Page

Selection and ordering data

- For snap-on and screw mounting 4/46

Technical data	4/46
Description	4/46
Dimensions	4/54

Residual-current devices



Residual-current devices

Page

Selection and ordering data

- 3UL21 tripping relay 4/47
- 3UL22 summation current transformer 4/47

Technical data	4/47
Description	4/48
Typical circuit diagrams	4/49
Dimensions	4/55